

Objective

- Provide Investigators and Damage Control Personnel with actual pics of casualty damage so that they may understand what they are seeing and then provide better reporting service to the DC Repair Stations and DC Central.
- These pics become invaluable for training and help personnel gain knowledge to rapidly identify unknown damage for rapid intervention.

MISSILE IMPACT



COMPARTMENT DEMOLISHED

2-100-1-L



SAGGING OVERHEAD



WARPED BULKHEAD



PANTING BULK HEAD



SPRUNG DOOR



JAMMED DOOR



HOT SPOT WTD




CONTROLLER FIRE



SWITCH BOARD FIRE



HOLE 2-292-2-Q HT SHOP



HOLE IN CCS 2-292-01-C

